



OFFICE OF THE ILLINOIS STATE FIRE MARSHAL
Division of Petroleum and Chemical Safety
1035 Stevenson Drive
Springfield, Illinois 62703-4259
(217)785-1020

FOR OFFICE USE ONLY

Facility # 4-009767
Permit # 00014-2014UPG
Request Rec'd 01/08/2014
Amended Date 04/07/2014
Approval Date 1/8/2014 JC
Permit Expires 7/8/2014

Amended

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) OWNER OF TANKS - Corporation, partnership, or other business entity: Kraft Foods Global, Inc. 1701 W. Bradley Ave. Champaign, IL 61821 Contact: Jerry Ragland (847) 323-5804	(2) FACILITY - name and address where tanks are located: Kraft Foods Global, Inc. 1701 W. Bradley Ave. Champaign, Champaign Co., IL Contact: Elbow Mark (217) 378-2538
---	---

(3) UPGRADE OR REPAIR OF TANKS:

(a) *Number and size of tanks being upgraded or repaired:* (TK # 10) - 15,000 gallons

(b) *Type of tanks:*

(c) *Type of piping:*

(d) *Product to be stored in each tank:* (TK # 10) - Diesel Fuel

(e) *Type of leak detection being used:*

Tank: (TK # 10) - **(Installing) Interstitial Monitoring Veeder Root TLS 350 for tank leak detection**, (TK # 10) - **(Installing) Automatic Tank Gauging Veeder Root TLS 350 console and probe for inventory purposes only.**

Piping: (TK # 10) - **(Installing) Piping Sump Sensors Interstitial Monitoring Veeder Root TLS 350 (one will be located at the submersible sump, and one will be located at the existing transition sump located near the second island / dispenser only - reference site plan from permit #01308-2002UPG and 01793-2002UPG for location of this transition sump near the second island if necessary).**

(f) *Corrosion Protection being used:*

Tank:

Piping:

(g) *Spill containment devices, piping, and dispenser containment devices:*

(h) *Overfill prevention devices:*

(i) *Manway accessible at grade:*

(4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) **SPECIAL CONTINGENCIES:** Amendment request was received 04/07/14. A tank interstitial monitor will be added for leak detection and the tank gauge will be used for inventory purposes only. Also, the piping sump interstitial sensors will be installed at the submersible sump and at the transition sump near the second island.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK: Illinois Oil Marketing Equipment, Inc. 850 Brenkman Drive Pekin, IL 61554	Contact Person: Chris Epkins Phone: (309) 347-1819 Contractor Registration # IL-1293 Exp. 02/04/2014
--	--

Sincerely,

Jim Coffey

cc: Storage Tank Safety Specialist -
Fire Department -
Division File
(Rev. - 9/10)