

OFFICE OF THE ILLINOIS STATE FIRE MARSHAL

Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, Illinois 62703-4259 (217)785-1020

FOR OFFICE USE ONLY

Facility # 2-041586 Permit # 00565-2014UPG Request Rec'd 06/17/2014 Amended Date Approval Date 6/17/2014 JC Permit Expires 12/17/2014

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
Costco Wholesale Corporation 999 Lake Drive Isaquah, WA 98027	Costco Wholesale 1332 South Route 59 Naperville, Du Page Co., IL
Contact: Dennis Bock (425) 313-4725	Contact: Dennis Bock (425) 313-6048

(3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2, 3) 20,000 gallons, (TK # 4) 1,500 gallons
- (b) Type of tanks:
- (c) Type of piping: (TK # 1, 2, 3, 4) (Installing) partial Flexible Double Wall OPW Flexworks HDPE non corrosive from the last two existing dispenser sumps to four new dispensers, (TK # 1, 2, 3, 4) (Installing) Dispenser Sumps containment FRP (four total, to accommodate the installation of four new dispensers).
- (d) Product to be stored in each tank: (TK # 1, 2, 3) Gasoline, (TK # 4) Lubrizol Fuel Additive
- (e) Type of leak detection being used:

Tank:

Piping: (TK # 1, 2, 3, 4) - (Installing) Piping Sump Sensors Interstitial Monitoring Veeder Root TLS 350 at the four new dispenser sumps only (there are existing sensors at the last two existing dispenser sumps per 02533-2003INS).

(f) Corrosion Protection being used:

Tank:

Piping: (TK # 1, 2, 3, 4) - (Installing) partial Flexible Non-Corrosive

- (g) Spill containment devices, piping, and dispenser containment devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) SPECIAL CONTINGENCIES:

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Anderson Pump Service, Inc. 19659 South 97th Avenue

Mokena, IL 60448

Contact Person: Hoyt Ary Phone: (708) 243-9081

Contractor Registration # IL-002275 Exp. 05/21/2016

Sincerely,

Jim Coffey

James of Coffey