

OFFICE OF THE ILLINOIS STATE FIRE MARSHAL

Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, Illinois 62703-4259 (217)785-1020

FOR OFFICE USE ONLY

Facility # 2-040615 Permit # 01200-2014UPG Request Rec'd 12/17/2014 Amended Date Approval Date 12/17/2014 DS Permit Expires 6/17/2015

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) OWNER OF TANKS - Corporation, partnership, or other business entity:

Meijer Great Lakes Limited Partnership
2929 Walker Avenue, NW
Grand Rapids, MI 49544-9428
Contact: Lyle Livasy (616) 453-6711

(2) FACILITY - name and address where tanks are located:

Meijer Gas Station #215
735 E Boughton Road
Bolingbrook, Will Co., IL

Contact: Bruce Dillow (630) 783-5300

(3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 3) 8,000 gallons
- (b) Type of tanks:
- (c) Type of piping: (TK # 3) (Installing) Partial Fiberglass Double Wall NOV Fiberglass Systems Red Thread IIA fiberglass piping to existing dispenser
- (d) Product to be stored in each tank: (TK # 3) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping: (TK # 3) - (Installing) Piping Sump Sensors Interstitial Monitoring Veeder Root TLS 350 Plus

(f) Corrosion Protection being used:

Tank:

Piping: (TK # 3) - (Installing) Fiberglass Non-Corrosive

- (g) Spill containment devices, piping, and dispenser containment devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) SPECIAL CONTINGENCIES:

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Stenstrom Petroleum Services Group
2422 Center Street

Contact Person: Nate Meyer
Phone: (815) 398-6250

Rockford, IL 61108 Contractor Registration # IL-1890 Exp. 03/07/2016

Sincerely,

Daniel Starks

Vaniel J. Starke

cc: Storage Tank Safety Specialist -Fire Department -Division File (Rev. - 9/10)