



OFFICE OF THE ILLINOIS STATE FIRE MARSHAL  
Division of Petroleum and Chemical Safety  
1035 Stevenson Drive  
Springfield, Illinois 62703-4259  
(217)785-1020

FOR OFFICE USE ONLY

Facility # 2-021622  
Permit # 00033-2015UPG  
Request Rec'd 01/14/2015  
Amended Date  
Approval Date 1/15/2015 JC  
Permit Expires 7/15/2015

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

<b>(1) OWNER OF TANKS</b> - Corporation, partnership, or other business entity: Thornton's, Inc. 10101 Linn Station Road, P.O. Box 34230 Louisville, KY 40223 Contact: Scott Roberts (800) 928-8022	<b>(2) FACILITY</b> - name and address where tanks are located: Thornton #9 800 West Lake Street Addison, Du Page Co., IL Contact: John Muller (630) 543-7511
---	---

**(3) UPGRADE OR REPAIR OF TANKS:**

- (a) *Number and size of tanks being upgraded or repaired:* (TK # 9) - 6,000 gallons
- (b) *Type of tanks:*
- (c) *Type of piping:* (TK # 9) - (Repairing) the existing shear valve at dispenser sump # 14 only (see contingencies section for further details).
- (d) *Product to be stored in each tank:* (TK # 9) - Diesel Fuel
- (e) *Type of leak detection being used:*
  - Tank:*
  - Piping:*
- (f) *Corrosion Protection being used:*
  - Tank:*
  - Piping:*
- (g) *Spill containment devices, piping, and dispenser containment devices:*
- (h) *Overfill prevention devices:*
- (i) *Manway accessible at grade:*

- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at [www.sfm.illinois.gov](http://www.sfm.illinois.gov) or by calling (217)785-1020.

- (5) **SPECIAL CONTINGENCIES:** This permit is essentially replacing permit #00532-2014UPG; however, the contractor indicates the shear valve is actually being repaired rather than replaced (the original permit application indicated the shear valve was going to be replaced). The contractor indicates the fusible link arm of the shear valve had to be repaired.

<b>(6) PERSON, FIRM OR COMPANY PERFORMING WORK:</b> Beacon SSI, Inc. 2413 South 7th Avenue North Riverside, IL 60546	Contact Person: Patrick Ferriter or Bill Welch Phone: 630-207-1713 Contractor Registration # IL-002336 Exp. 01/27/2015
---	--

Sincerely,

Jim Coffey

