



OFFICE OF THE ILLINOIS STATE FIRE MARSHAL
Division of Petroleum and Chemical Safety
 1035 Stevenson Drive
 Springfield, Illinois 62703-4259
 (217)785-1020

<u>FOR OFFICE USE ONLY</u>
Facility # 5-001140
Permit # 00055-2015UPG
Request Rec'd 01/20/2015
Amended Date
Approval Date 1/22/2015 JC
Permit Expires 7/22/2015

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

<p>(1) OWNER OF TANKS - Corporation, partnership, or other business entity: Meera Shakti, Inc. / Meera, LLC 405 W. Elm Street Waverly, IL 62692-1088 Contact:</p>	<p>(2) FACILITY - name and address where tanks are located: Meera Shakti, Inc. / Meera, LLC 405 W. Elm Street Waverly, Morgan Co., IL Contact: Richard Fanning (217) 245-1441</p>
--	--

(3) UPGRADE OR REPAIR OF TANKS:

- (a) *Number and size of tanks being upgraded or repaired:* (TK # 5) - 6,000 gallons
- (b) *Type of tanks:*
- (c) *Type of piping:* (TK # 5) - (Installing) riser at the tank / ball float valve extractor fitting location to replace the existing leaking riser only (see contingencies section).
- (d) *Product to be stored in each tank:* (TK # 5) - Gasoline
- (e) *Type of leak detection being used:*
 Tank:
 Piping:
- (f) *Corrosion Protection being used:*
 Tank:
 Piping:
- (g) *Spill containment devices, piping, and dispenser containment devices:*
- (h) *Overfill prevention devices:*
- (i) *Manway accessible at grade:*

(4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) SPECIAL CONTINGENCIES: Contractor is replacing the ball float valve riser only. Contractor states he can isolate the riser from the tank and therefore will be able to air test the riser / vent line, and not have to air test the tank. Vent lines must be tested at 7 psi minimum or at a pressure recommended by the manufacturer. All steel risers, vents, and fills in contact with the ground, backfill or water shall be dielectrically wrapped or coated.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:	
Pemco Service Company, Inc. 1198 East Lincoln Street Riverton, IL 62561	Contact Person: Mike Milburn Phone: 217-629-8522 Contractor Registration # IL-1224 Exp. 02/23/2016

Sincerely,

Jim Coffey

cc: Storage Tank Safety Specialist -
Fire Department -
Division File
(Rev. - 9/10)