



Office of the Illinois State Fire Marshal  
Division of Petroleum and Chemical Safety  
1035 Stevenson Drive  
Springfield, IL 62703  
2177851020

**FOR OFFICE USE ONLY**

Facility # 3029397  
Permit # 00912-2015UPG  
Request Rec'd 09/01/2015  
Amended Date  
Approval Date 9/1/2015 DS  
Permit Expires 3/1/2016

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

<p>(1) <b><u>OWNER OF TANKS</u></b> - Corporation, partnership, or other business entity:</p> <p>Illinois Ayers Oil Company 6900 Hwy 24 East @ I-172 PO Box 772 Quincy, IL 62306</p> <p>Contact: Carl Adams Jr (217) 434-8662</p>	<p>(2) <b><u>FACILITY</u></b> - name and address where tanks are located:</p> <p>Ayerco #22 Convenience Center 318 West Jackson Street Macomb, IL 61455</p> <p>Contact: Amber Bilderback (217) 434-8662</p>
---	---

**(3) UPGRADE OR REPAIR OF TANKS:**

(a) *Number and size of tanks being upgraded or repaired: (TK # 2, 3) - 10,000*

(b) *Type of tanks:*

(c) *Type of piping: (TK # 3) Piping - Steel Single Wall Piping*

(d) *Product to be stored in each tank: (TK # 2) - Gasoline, (TK # 3) - Diesel Fuel*

(e) *Type of leak detection being used:*

*Tank:*

*Piping:*

(f) *Corrosion Protection being used:*

*Tank:*

*Piping: (TK # 2) Corrosion Prot - Piping - Sacrificial Anode Cathodic Protection*

(g) *Spill containment devices, piping, and dispenser containment devices:*

(h) *Overfill prevention devices: (TK # 2, 3) Overfill Prev Device - Ball Float Vent Valve Morrison 317*

(i) *Manway accessible at grade:*

(4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at [www.sfm.illinois.gov](http://www.sfm.illinois.gov) or by calling (217)785-1020.

**(5) SPECIAL CONTINGENCIES :**


installing a Morrison ball float 317 with a cage and housing 560-0100. with an 5 pound anode and coat and wrap al new 4" pipe  
the housing for the ball valve will be taken off the vent line and all new going back.

**(6) PERSON, FIRM OR COMPANY PERFORMING WORK:**

R. L. Hoener Company  
2923 Gardner Expressway P. O. Box 1086  
Quincy, IL 62305

Contact Person: Marty Jackson  
Phone: (217) 223-2190  
Contractor Registration # IL2021 Exp. 5/22/2016

Sincerely,

  
\_\_\_\_\_

Daniel Starks

**cc:** Storage Tank Safety Specialist  
Division File