

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety 1035 Stevenson Drive Springfield, IL 62703 2177851020

## FOR OFFICE USE ONLY

Facility # 2029288 Permit # 01401-2015UPG Request Rec'd 12/14/2015 Amended Date Approval Date 12/16/2015 DS Permit Expires 6/16/2016

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
Ahmad Zahdan-Five M Oil, Inc. 10017 S. Menard Ave. Oak Lawn, IL 60453	Pal Mart, Inc. 415 New Avenue Romeoville, IL 60441
Contact: Ahmad Zahdan (708) 372-7632	Contact: Jibby Thomas (708) 253-9293

## (3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 2) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 2) Piping Fiberglass Single Wall Piping Ameron, (TK # 2) Piping Shear Valves, (TK # 2) Piping Dispenser Sumps containment FRP, (TK # 2) Piping Sumps Entry Boots
- (d) Product to be stored in each tank: (TK # 2) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u> : Excavated to expose all piping in island area and found piping to be 2" single wall Ameron at the islands. The Premium line had a hole in it. Will repair with less than 20' of Ameron single wall FRP pipe.

## (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Omblis, Inc. 24325 Leski Lane Plainfield, IL 60585 Contact Person: Kiran Madhu Phone: (630) 649-8699 Contractor Registration # IL002410 Exp. 8/10/2017 Sincerely, Daniel J. Starks

Daniel Starks

cc: Storage Tank Safety Specialist Division File