

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety 1035 Stevenson Drive Springfield, IL 62703 2177851020

# Amended

FOR OFFICE USE ONLY

Facility # 2029288 Permit # 01401-2015UPG Request Rec'd 12/14/2015 Amended Date 12/23/2015 Approval Date 12/16/2015 DS Permit Expires 6/16/2016

### Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
Anmad Zandan-Five M Oil, Inc. 10017 S. Menard Ave	Pal Mart, Inc. 415 New Avenue Romeoville, IL 60441
Contact: Ahmad Zahdan (708) 372-7632	Contact: Jibby Thomas (708) 253-9293

#### (3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2, 3) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1, 2, 3) Piping Fiberglass Single Wall Piping Ameron Dualoy 3000L single wall fiberglass piping, (TK # 1, 2, 3) Piping Shear Valves, (TK # 1, 2, 3) Piping Dispenser Sumps OPW DS-1000 Series
- (d) Product to be stored in each tank: (TK # 1, 2) Gasoline, (TK # 3) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

## (5) <u>SPECIAL CONTINGENCIES</u> :

Cutting into all three product lines (tanks 1,2,3) to bring into the under dispenser containment sump. Less than 20' of 2" fiberglass on each line.

## (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Omblis, Inc. 24325 Leski Lane Contact Person: Kiran Madhu Phone: (630) 649-8699 Plainfield, IL 60585

Sincerely,

Daniel J. Starke

Daniel Starks

cc: Storage Tank Safety Specialist Division File