

#### Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

## **FOR OFFICE USE ONLY**

Facility # 6024460 Permit # 00004-2016UPG Request Rec'd 12/31/2015 Amended Date Approval Date 1/4/2016 DS Permit Expires 7/6/2016

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Clinton County Oil Company, Inc.

P.O. Box 155 Breese, IL 62230

Contact: Gene Bickl (618) 526-7570

(2) FACILITY - name and address where tanks are located:

C C Food Mart Route 161 & White Oaks Drive New Baden, IL 62265

Contact: Madelyne Coleman (618) 526-7291

#### (3) **UPGRADE OR REPAIR OF TANKS:**

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2) 10,000, (TK # 3) 12,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1, 2, 3) Piping Fiberglass Single Wall Piping, (TK # 1, 2, 3) Piping Dispenser Sumps OPW DS-1000 Series, (TK # 1, 2, 3) Piping Flex Connector Steel
- (d) Product to be stored in each tank: (TK # 1, 2, 3) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

## (5) <u>SPECIAL CONTINGENCIES</u>:

Site has NOV for incorrect shear valve heights

We propose to remove gasoline islands and install OPW dispenser sumps just above grade. Further, we will modify existing singlewall FRP into new sumps, plus new stainless steel flex hoses and new shear valves. Diesel island, we will beakout concrete and adjust heighth on piping run to allow existing shear valve to be adjusted to correct height. No dispenser sump or island work to be done.

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

UPC Enterprises, LC d/b/a United Petroleum Service 1458 Collins Street St. Louis, MO 63102 Contact Person: Harvey Stokes Phone: (314) 241-3767

Contractor Registration # IL002402 Exp. 2/10/2016

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File