

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2002739 Permit # 00062-2016UPG Request Rec'd 01/19/2016 Amended Date Approval Date 1/19/2016 DS Permit Expires 7/19/2016

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business

entity:

Bukhari Food Mart, Inc.

6900 Canton

Lincolnwood, IL 60645

Contact: Fazil Yaqoob (847) 338-7278

(2) FACILITY - name and address where tanks are located:

Marathon

3800 West Oakton Street

Skokie, IL 60076

Contact: Akhter Raza (847) 982-0901

(3) **UPGRADE OR REPAIR OF TANKS:**

- (a) Number and size of tanks being upgraded or repaired: (TK # 11) 6,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 11) Piping Submersible Sumps OPW Fiberglass
- (d) Product to be stored in each tank: (TK # 11) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) <u>SPECIAL CONTINGENCIES</u>:

Cut piping and conduits away from sump.

Remove existing cracked poly sump on Tank #11 (Premium) and replace with fiberglass sump.

Reinstall piping into sump and reconnect to submersible.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Omblis, Inc. Contact Person: Kiran Madhu

Phone: (630) 649-8699 Contractor Registration # IL002410 Exp. 8/10/2017

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File