

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2010033 Permit # 00087-2016UPG Request Rec'd 01/26/2016 Amended Date Approval Date 1/27/2016 DS Permit Expires 7/27/2016

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business

entity:

Mokena Gas, LLC 975 Westshore Blvd. Manteno, IL 60950

Contact: Paul Torstrick (815) 922-0203

(2) FACILITY - name and address where tanks are located:

Gas Buster / Mobil 19301 96th Ave. Mokena, IL 60950

Contact: Paul Torstrick (815) 922-0203

(3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 3) 12,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 3) Piping Submersible Sumps Franklin Fueling Systems 4736 Series Polyethylene
- (d) Product to be stored in each tank: (TK # 3) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping: (TK # 3) Leak Detect - Piping - Piping Sump Sensors Interstitial Monitoring Veeder Root TLS 350

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) <u>SPECIAL CONTINGENCIES</u>:

Excavating and removing existing reg sub pump installing new enclosure with VR sump sensor

hydrostacily test enclosure independent third person to test piping. Please note that sump sensors are not required per our rules for single wall piping.

BMPC, Inc. 1510 Spring Bay Road, Unit E East Peoria, IL 61611 Contact Person: Amanda McCormick Phone: (309) 208-5264 Contractor Registration # IL002393 Exp. 12/12/2016

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File