

### Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

## Permit for Emergency Repair Request on 3/8/2016

## **FOR OFFICE USE ONLY**

Facility # 5017274
Permit # 00246-2016UPG
Request Rec'd 03/08/2016
Amended Date
Approval Date 3/8/2016 DS
Permit Expires 3/21/2016

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

•

Jayvir, Inc.

101 E. Union Avenue Litchfield, IL 62056

Contact: Sanjay Patel (847) 208-5396

(2) FACILITY - name and address where tanks are located:

Amstar

101 E. Union Avenue Litchfield, IL 62056

Contact: Lucinda Werner (217) 324-4641

### (3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 3) 6,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 3) Piping Steel Single Wall Piping
- (d) Product to be stored in each tank: (TK # 3) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

#### (5) <u>SPECIAL CONTINGENCIES</u>:

Repairing tank #3 product line which was damaged when contractor doing the adandment of the other 2 tanks hit the unleaded product line and caused

the coupling to leak. We are going to cut out about 3 feet of line and replace with new pipe and a union, then test the line and have it inspected.

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Pemco Service Company, Inc. 1040 East Second Street Contact Person: William "Butch" VonDrehle

Phone: (815) 265-7364

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File