

## Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

# **FOR OFFICE USE ONLY**

Facility # 2031280 Permit # 00350-2016UPG Request Rec'd 04/01/2016 Amended Date Approval Date 4/4/2016 DS Permit Expires 10/4/2016

# Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

.....

United States Postal Service 222 South Riverside Place - 1200 Chicago, IL 606066150

Contact: Lois Kimmelman (312) 669-5967

(2) FACILITY - name and address where tanks are located:

United States Postal Serv-VMF 500 East Fullerton Avenue Carol Stream, IL 60188

Contact: Rodger Elion (630) 260-5403

## (3) **UPGRADE OR REPAIR OF TANKS:**

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2) 10,000, (TK # 3) 550
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 1) Gasoline, (TK # 2) Diesel Fuel, (TK # 3) Used Oil
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices: (TK # 1, 2, 3) Overfill Prev Device Overfill Alarm Veeder Root TLS 350
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

## (5) <u>SPECIAL CONTINGENCIES</u>:

Installing Veeder Root Overfill Alarm with Acknowledgement Switch PN 790091-001 and 790095-001 and Relay Output Module 329359-001.

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Anderson Pump Service, Inc. 19659 South 97th Avenue Mokena, IL 60448 Contact Person: Rick Krol Phone: (708) 478-6190

Contractor Registration # IL002275 Exp. 5/21/2016

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File