

Office of the Illinois State Fire Marshal **Division of Petroleum and Chemical Safety**

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 4043703 Permit # 00485-2016UPG Request Rec'd 04/29/2016 Amended Date Approval Date 5/2/2016 DS Permit Expires 11/2/2016

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) **OWNER OF TANKS** - Corporation, partnership, or other business

entity:

Meijer Great Lakes Limited Partnership 2929 Walker Avenue, NW Grand Rapids, MI 495449428

Contact: Brian Honsfud (616) 791-5778

(2) FACILITY - name and address where tanks are located:

Meijer Gas Station #247 2602 S. Philo Road Urbana, IL 61802

Contact: Taylor Fears (217) 365-5229

(3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 4) 8,000, (TK # 2) 20,000, (TK # 3, 5) 6,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1, 2, 3, 4, 5) Piping Valves Ball Valve, (TK # 1, 2, 3, 4, 5) Piping Flex Connector Steel
- (d) Product to be stored in each tank: (TK # 1, 2) Gasoline, (TK # 3, 4) Diesel Fuel, (TK # 5) E-85
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) SPECIAL CONTINGENCIES: Installing new Jomar stainless steel ball valves and HoseMaster stainless steel flex connectors at all submersible containment sumps. NOTE: If there are not sumps existing where piping is being broken, ones must be installed per 175.410

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Stenstrom Petroleum Services Group 2422 Center Street Rockford, IL 61108

Contact Person: Nate Meyer Phone: (815) 398-6250

Contractor Registration # IL1890 Exp. 3/7/2018

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File