

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety 1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 6011109 Permit # 00772-2016UPG Request Rec'd 06/24/2016 Amended Date Approval Date 6/27/2016 DS Permit Expires 7/8/2016

Permit for Emergency Repair Request on 6/23/2016

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
Moto Inc	Monsanto Moto Mart 3120 Mississippi Avenue East St. Louis, IL 62206 Contact: Lisa Davis (618) 332-8634

(3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 7) 12,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 7) Piping Other elbow fitting
- (d) Product to be stored in each tank: (TK # 7) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfmillinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: We hade to loosen the union at the submerged pump and remove the steel pipe fittings in the sump to clean and reassemble. No fittings were changed, we just had to tighten and re assemble to stop the weeping. NOTE: If there was no existing submersible sump one must be installed under a separate upgrade permit per 175.410 b)

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

UPC Enterprises, LC d/b/a United Petroleum Service 1458 Collins Street St. Louis, MO 63102 Contact Person: Harvey Stokes Phone: (314) 241-3767 Contractor Registration # IL002402 Exp. 2/10/2018 Sincerely, Daniel J. Starks

Daniel Starks

cc: Storage Tank Safety Specialist Division File