

#### Office of the Illinois State Fire Marshal **Division of Petroleum and Chemical Safety**

1035 Stevenson Drive Springfield, IL 62703 2177851020

# Permit for Emergency Repair Request on 8/4/2016

## **FOR OFFICE USE ONLY**

Facility # 2013826 Permit # 00960-2016UPG Request Rec'd 08/03/2016 Amended Date Approval Date 8/3/2016 DS Permit Expires 8/16/2016

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) **OWNER OF TANKS** - Corporation, partnership, or other business

entity:

MPCO Real Estate, LLC 100 Tri State International, Suite 100 Lincolnshire, IL 60069

Contact: Furrukh Bagasarawala (847) 845-6051

(2) FACILITY - name and address where tanks are located:

Joliet Marathon 324 South Larkin Ave Joliet, IL 60431

Contact: Sid (630) 890-7473

#### (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 6, 7) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 6, 7) Piping Shear Valves, (TK # 6, 7) Piping Flex Connector Steel
- (d) Product to be stored in each tank: (TK # 6, 7) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Per Protanic Testing the flex connector for the Premium product in dispenser sump #1/2, and the flex connector for the Midgrade product in dispenser sump #3/4, failed the line test and will be replaced with Hose Master, Fire Shield, stainless steel flex connectors. The existing shear valves connected to the flexes may also have to be changed. NOTE: If there is NOT currently a sump where piping is being broken one must be installed per 175.410 d)

## (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

B & K Equipment Company 2939 175th Street Lansing, IL 60438

Contact Person: Ed Angell Phone: (708) 474-3344 Contractor Registration # IL1207 Exp. 2/14/2018 Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File