

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2013485 Permit # 01543-2016UPG Request Rec'd 12/06/2016 Amended Date Approval Date 12/7/2016 DS Permit Expires 6/7/2017

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business

entity:

Akzo Nobel Coatings, Inc. 1 East Water Street Waukegan, IL 60085

Contact: Chuck Morris (847) 687-7100

(2) FACILITY - name and address where tanks are located:

Akzo Nobel Coatings Inc 1 East Water Street Waukegan, IL 60085

Contact: Cherylyn McHugh (847) 687-7100

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 62, 66, 70, 73, 76) 12,000, (TK # 63, 77) 9,000, (TK # 64, 65, 68, 69, 78) 3,000, (TK # 67, 71, 72, 74, 75) 6,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78) Hazardous Substance
- (e) Type of leak detection being used:

Tank: (TK # 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78) Leak Detect - Tank - Automatic Tank Gauging Incon TS-550 evo automatic tank gauge, (TK # 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78) Leak Detect - Tank - Interstitial Monitoring Incon TSP ULS

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Franklin Fueling (Incon) T5000evo Monitor for level monitoring and sensor monitoring. There are 5 compartmentalized double wall tanks. Compartments total 17 as indicated by the tank #s. 5 TSP-ULS sensors will be installed in the five tank interstices.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Contact Person: Dan McMahon

Interstate Pump & Tank, Inc. 901 Niagara Street Waukesha, WI 53186 Phone: (262) 524-8494 Contractor Registration # IL1171 Exp. 5/7/2018

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File