

### Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

### **FOR OFFICE USE ONLY**

Facility # 2014688 Permit # 00187-2017UPG Request Rec'd 02/14/2017 Amended Date Approval Date 2/21/2017 DS Permit Expires 8/22/2017

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Hanover Food Mart, Inc.

8060 Lawndale Ave. Skokie, IL 60076

Contact: Hafiz Yaqoob (847) 322-6864

(2) FACILITY - name and address where tanks are located:

Hanover Gas Station 7401 Jensen Blvd. Hanover Park, IL 60133

Contact: Hafiz Yaqoob (847) 322-6864

## (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 8) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 8) Piping Submersible Sumps Bravo B-400 Series
- (d) Product to be stored in each tank: (TK # 8) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Due to the motor head oring is leaking the bolts are corroded the testing company TANKNOLGY cannot do the testing

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Omblis, Inc.

Contact Person: Kiran Madhu
24325 Leski Lane
Phone: (630) 649-8699
Plainfield, IL 60585

Contractor Registration # IL00

Contractor Registration # IL002410 Exp. 10/11/2018

**~**·

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File