

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety 1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2033378 Permit # 00377-2017UPG Request Rec'd 03/29/2017 Amended Date Approval Date 4/3/2017 DS Permit Expires 10/3/2017

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
Vulcan Materials Company 1000 East Warrenville Rd Suite 100 Naperville, IL 60563	Vulcan Construction Materials LLC 1520 Midway Court Elk Grove Village, IL 60007 Contact: George Lunsford (630) 816-8573
Contact. Recekan Schulehoerg (050) 201-8000	

(3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 2) 12,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 2) Piping Shear Valves
- (d) Product to be stored in each tank: (TK # 2) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfmillinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Adjusting piping underneat dispenser to relocate shear valve at the appropriate height compared to the island. Currenty the shear valve sits 1" to high. A new shear valve is also being installed. NOTE: If there is no dispenser sump where piping is being broken one must be installed per 175.410 d)

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Accurate Tank Technologies, Inc. 204 Poplar Place North Aurora, IL 60542 Contact Person: Steve Hirsch Phone: (630) 375-6121 Ext. 10 Contractor Registration # IL1594 Exp. 8/15/2018 Sincerely,

Daniel J. Starke

Daniel Starks

cc: Storage Tank Safety Specialist Division File