

## Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

#### **FOR OFFICE USE ONLY**

Facility # 4020234 Permit # 00571-2017UPG Request Rec'd 05/19/2017 Amended Date Approval Date 5/22/2017 DS Permit Expires 11/22/2017

#### Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Material Service Corporation 470 W. 172nd Street Thornton, IL 60476

Contact: Randy Boisvert (708) 731-2599

(2) FACILITY - name and address where tanks are located:

Material Service Corporation 3706 Catlin - Homer Road Limestone Quarry, Yard 16 Fairmount, IL 61841

Contact: Kelly O'Brien (217) 733-2139

### (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 4) 10,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK#4) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping: (TK # 4) Leak Detect - Piping - Piping Sump Sensors Interstitial Monitoring Veeder Root TLS 350 interstitial piping float sensor

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Remove existing sump sensor (single wall piping) under this permit and installing CP under Permit #00553-2017CAT

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Midwest Petroleum Service, LLC. 23535 North 1530 East Road Danville, IL 61834 Contact Person: Mike Hall Phone: (217) 443-2263

Contractor Registration # IL002306 Exp. 6/26/2018

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File