

### Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

## Permit for Emergency Repair Request on 7/5/2017

#### **FOR OFFICE USE ONLY**

Facility # 2016676 Permit # 00793-2017UPG Request Rec'd 07/06/2017 Amended Date Approval Date 7/6/2017 DS Permit Expires 7/18/2017

#### Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business

entity:

Glenmill Petroleum, Inc. 4118 Hampton Court Glenview, IL 60026

Contact: Anish Chittakattu (773) 793-3583

(2) FACILITY - name and address where tanks are located:

Glenmill Petroleum, Inc. d/b/a Citgo 825 Milwaukee Avenue Glenview, IL 60025

Contact: Anish Chittakattu (773) 793-3583

#### (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 7, 8) 12,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 7, 8) Piping Galvanized Steel Single Wall Piping, (TK # 7, 8) Piping Valves Ball Valve, (TK # 7, 8) Piping Flex Connector Steel
- (d) Product to be stored in each tank: (TK # 7, 8) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Repipe both Regular product submersible pump sumps due to leaking fittings from a previous line leak detection system that is no longer in use per violation Notice dated 6/29/17. Stainless Steel flex connectors and ball valves will also be replaced for both tanks.

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

B & K Equipment Company 2939 175th Street Lansing, IL 60438

Contact Person: Ed Angell Phone: (708) 474-3344 Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File