

### Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

### **FOR OFFICE USE ONLY**

Facility # 2021174 Permit # 00811-2017UPG Request Rec'd 07/10/2017 Amended Date Approval Date 7/10/2017 DS Permit Expires 1/10/2018

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

RDK Ventures, LLC 550 Warrenville Rd., Suite 400 Lisle, IL 60532

Contact: Charlene Troyer (630) 800-6065

(2) FACILITY - name and address where tanks are located:

Circle K #6728 930 East Roosevelt Road Lombard, IL 60148

Contact: Maria Rodrguez (812) 379-9227

## (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2, 3) 12,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1) Piping Shear Valves
- (d) Product to be stored in each tank: (TK # 1, 2, 3) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping: (TK # 1, 2, 3) Leak Detect - Piping - Piping Sump Sensors Interstitial Monitoring Veeder Root TLS 350 discriminating containment sump

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) SPECIAL CONTINGENCIES: Remove Beaudreau sensors and install Veeder Root wireless discriminating sensor 857080-111. NOTE: Sensors must have the capability to shut down the stp supplying that line upon the detection of a leak, per section 175.640 a) 2) Replace shear valve under dispenser 11/12 RUL. NOTE: If there is not an existing dispenser sump one must be installed per 175.410 d) Install intercom to all dispensers.

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Anderson Pump Service, Inc. 19659 South 97th Avenue Contact Person: Ron Anderson Phone: (708) 478-6190 Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File