



Office of the Illinois State Fire Marshal  
Division of Petroleum and Chemical Safety  
1035 Stevenson Drive  
Springfield, IL 62703  
2177851020

**FOR OFFICE USE ONLY**

Facility # 5024404  
Permit # 01590-2017UPG  
Request Rec'd 12/20/2017  
Amended Date  
Approval Date 12/20/2017 DS  
Permit Expires 6/20/2018

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

<p><b>(1) <u>OWNER OF TANKS</u></b> - Corporation, partnership, or other business entity:</p> <p>NF Properties, LLC 1501 North 12th Street Quincy, IL 62301</p> <p>Contact: Andy Hermsmeier (217) 221-5628</p>	<p><b>(2) <u>FACILITY</u></b> - name and address where tanks are located:</p> <p>County Market Express #791 301 Riverview Quincy, IL 62301</p> <p>Contact: Jeremy Dyer (217) 221-5628</p>
--	---

**(3) UPGRADE OR REPAIR OF TANKS:**

- (a) Number and size of tanks being upgraded or repaired: (TK # 1) - 8,000*
- (b) Type of tanks:*
- (c) Type of piping: (TK # 1) Piping - Fiberglass Single Wall Piping Ameron Dualoy 3000L single wall fiberglass piping, (TK # 1) Piping - Other elbow fitting, (TK # 1) Piping - Other Fiberglass Male Bell Fitting, (TK # 1) Piping - Valves Ball Valve, (TK # 1) Piping - Submersible Sumps Franklin Fueling Systems 4736 Series Polyethylene, (TK # 1) Piping - Flex Connector Steel*
- (d) Product to be stored in each tank: (TK # 1) - Gasoline*
- (e) Type of leak detection being used:*
  - Tank:*
  - Piping:*
- (f) Corrosion Protection being used:*
  - Tank:*
  - Piping:*
- (g) Spill containment devices, piping, and dispenser containmnt devices:*
- (h) Overfill prevention devices:*
- (i) Manway accessible at grade:*

- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at [www.sfm.illinois.gov](http://www.sfm.illinois.gov) or by calling (217)785-1020.

- (5) **SPECIAL CONTINGENCIES** : Found bad flex connector. Break out concrete and remove existing sub pump. Cut existing single wall piping and install new tank sump. Re install sub pump and re route existing single wall piping into sump. Install new flex connector and ball valve. Make connection to sub pump and electrical. Test line. Hydro test sump. Back fill and set new manhole. Pour concrete. Have third party line test done. Call for final.

**(6) PERSON, FIRM OR COMPANY PERFORMING WORK:**

Contact Person: Steve Disselhorst

All Line Equipment, Inc.  
5519 Skyline Drive, PO Box 5257  
Quincy, IL 62305

Phone: (217) 224-9725  
Contractor Registration # IL002319 Exp. 12/23/2017

Sincerely,

A handwritten signature in cursive script that reads "Daniel H. Starks". The signature is written in dark ink and is positioned above a horizontal line.

Daniel Starks

cc: Storage Tank Safety Specialist  
Division File