

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2018378 Permit # 00006-2018UPG Request Rec'd 11/20/2017 Amended Date Approval Date 1/3/2018 DS Permit Expires 7/3/2018

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Thank GD Enterprises, Inc.

8060 North Lawndale Skokie, IL 60076

Contact: Mahmood Lakha (847) 679-7158

(2) <u>FACILITY</u> - name and address where tanks are located:

Union Seger Food Inc. 3400 South Union Avenue Steger, IL 60675

Contact: Lakha Ibtasam (847) 679-5398

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 9) 8,000, (TK # 10) 12,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 9, 10) Piping Fiberglass Double Wall Ameron Dualoy 3000/LCX, (TK # 9, 10) Piping Shear Valves, (TK # 9, 10) Piping Valves Ball Valve, (TK # 9, 10) Piping Submersible Sumps Franklin Fueling Systems 4542 Series Polyethylene, (TK # 9, 10) Piping Flex Connector Steel
- (d) Product to be stored in each tank: (TK # 9, 10) Gasoline
- (e) Type of leak detection being used:

Tank: (TK # 9, 10) Leak Detect - Tank - Automatic Tank Gauging Veeder Root TLS 350

Piping: (TK # 9, 10) Leak Detect - Piping - Electronic Pressurized Line Leak Detection Veeder Root TLS 350, (TK # 9, 10) Leak Detect - Piping - Piping Sump Sensors Interstitial Monitoring Veeder Root 794380-208 Non-Discriminating Sump Sensor

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: REMOVE OLD PIPE INSTALL NEW DW LCX AMERON. REMOVE EXISTING REDJACKET ST 1400 AND INSTALL VEEDEROOT TLS 350

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

BMPC, Inc. 1510 Spring Bay Road, Unit E Contact Person: Amanda McCormick

Phone: (309) 208-5264

Contractor Registration # IL002393 Exp. 12/12/2018

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File