

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety 1035 Stevenson Drive Springfield, IL 62703 2177851020

## FOR OFFICE USE ONLY

Facility # 2027224 Permit # 00222-2018UPG Request Rec'd 02/26/2018 Amended Date Approval Date 2/27/2018 DS Permit Expires 8/28/2018

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
6400 S Archer Ave	Ingredion, Inc. 6400 S. Archer Ave. Bedford Park, IL 60501
Contact: Rob Mead (708) 563-5334	Contact: Rob Mead (708) 563-5334

## (3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 1) 1,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 1) Gasoline
- (e) Type of leak detection being used:

Tank: (TK # 1) Leak Detect - Tank - Ground Water Monitoring Electronic

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:

(i) Manway accessible at grade:

- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfmillinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Remove and eliminate the groundwater sensor in the monitoring well. Use the interstitial sensor as the form of leak detection for the tank.

## (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Beacon SSI, Inc. 2413 South 7th Avenue North Riverside, IL 60546

Contact Person: Patrick Ferriter Phone: (708) 917-2263 Contractor Registration # IL002336 Exp. 1/27/2019 Sincerely,

Daniel J. Starke

Daniel Starks

cc: Storage Tank Safety Specialist Division File