

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 5032599 Permit # 00228-2018UPG Request Rec'd 02/28/2018 Amended Date Approval Date 2/28/2018 DS Permit Expires 8/28/2018

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Casey's Retail Company P.O. Box 3001 3305 SE Delaware Ave. Ankeny, IA 50021

Contact: Jill Reams-Widder (515) 965-6238

(2) FACILITY - name and address where tanks are located:

Casey's General Store #1758 723 State Jerseyville, IL 62052

Contact: Jill Reams-Widder (515) 965-6238

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1, 2) Piping Other submersible pump, (TK # 1, 2) Piping Valves Ball Valve, (TK # 1, 2) Piping Flex Connector Steel
- (d) Product to be stored in each tank: (TK # 1, 2) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping: (TK # 1, 2) Leak Detect - Piping - Electronic Pressurized Line Leak Detection Veeder Root TLS 350 Plus

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 1, 2) Spill Contain Device Manhole Pre-manufactured EBW 705 CIGKT Defender Single Wall
- (h) Overfill prevention devices: (TK # 1, 2) Overfill Prev Device Overfill Drop Tube Valve OPW 61SOP
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Tank # 1 & # 2 installing new EBW 705 series 5 gallon spill containment, OPW 61SOP-4012 Poppet coaxial over fill drop tubes, new FE Petro 1 1/2 hp submersibles with new flex connector & ball valve, & Veeder Roor PLLD Electronic line leak detection. Fiberglassing on new Franklin Fueling tank sump lids. **NOTE: If there are no existing submersible sumps where piping is being broken ones must be installed per 175.410 b)**

Seneca Companies, Inc. 4140 East 14th Street PO Box 3360 Des Moines, IA 50313 Contact Person: Keri Hankins Phone: (816) 761-1270 Contractor Registration # IL598 Exp. 2/23/2020

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File