

#### Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

## **FOR OFFICE USE ONLY**

Facility # 4017256 Permit # 00447-2018UPG Request Rec'd 04/13/2018 Amended Date Approval Date 4/16/2018 DS Permit Expires 10/16/2018

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) OWNER OF TANKS - Corporation, partnership, or other business

entity:

Jensen BP

600 West Praire Street Odell, IL 60460

Contact: Monte Jensen (815) 998-2642

(2) <u>FACILITY</u> - name and address where tanks are located:

Jensen's Amoco 600 W. Prairie Street Odell, IL 60460

Contact: Monte Jenson (815) 998-2642

### (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 7) 12,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 7) Piping Submersible Sumps Franklin Fueling Systems 4542 Series Polyethylene Single Wall
- (d) Product to be stored in each tank: (TK # 7) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Installing new Franklin Fueling APT submersible containment sump at ID #7 due to water intrusion. Reworking existing piping and electrical conduits to accommodate the new sump. Performing a nitrogen test on the piping and a hydrostatic test on the sump and penetrations after the replacement is complete. All set backs are existing.

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Total Petroleum Service Company 2421 Washington Road Contact Person: Greg McCoy Phone: (309) 694-8224 Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File