

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

Permit for Emergency Repair Request on 5/9/2018

FOR OFFICE USE ONLY

Facility # 2014573 Permit # 00581-2018UPG Request Rec'd 05/09/2018 Amended Date Approval Date 5/9/2018 DS Permit Expires 5/22/2018

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Speedway, LLC P.O. Box 1500

Springfield, OH 455011500

Contact: Eric Swaisgood (937) 863-6513

(2) FACILITY - name and address where tanks are located:

Speedway 7540 948 North Farnsworth Ave. Aurora, IL 60605

Contact: Store Manager (630) 851-4680

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 3) 12,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 3) Piping Flex Connector Steel
- (d) Product to be stored in each tank: (TK # 3) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) <u>SPECIAL CONTINGENCIES</u>:

Veeder Root detected a pressure loss and shut down the RUL line. After investigating we discovered a bad SS Flex Connector inside the existing submerge pump sump on tank # 3 We removed the old SS Flex Connector and replaced with a new one and related 2" steel fittings Small amount of gasoline was captured inside of sump. We pumped out and disposed of After the repair we ran a Veeder Rot .01 line test and it passed Owner will have a 3rd party independant test done.

DRW Services, Inc. 600 East Joe Orr Road Chicago Heights, IL 60411 Contact Person: Douglas Harmon Phone: (708) 758-3222 Contractor Registration # IL194 Exp. 3/10/2020

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File