

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

Permit for Emergency Repair Request on 5/14/2018

FOR OFFICE USE ONLY

Facility # 2007079 Permit # 00603-2018UPG Request Rec'd 05/15/2018 Amended Date Approval Date 5/15/2018 DS Permit Expires 5/29/2018

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

inity.

Speedway, LLC P.O. Box 1500

Springfield, OH 455011500

Contact: Eric Swaisgood (937) 863-6513

(2) FACILITY - name and address where tanks are located:

Speedway #5344 8301 Lemont Rd. Darien, IL 60515

Contact: Store Manager (630) 985-2203

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 8) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 8) Piping Shear Valves
- (d) Product to be stored in each tank: (TK # 8) B-11
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) <u>SPECIAL CONTINGENCIES</u>:

Under dispenser 11/12 the Diesel shear valve would not close and needed to be replaced We replaced with same OPW 10BF-5725 shear valve and anchored There is a containment sump in place Ran a Veeder Root .01 test and it passed Owner will have US Tank perfrom 3rd party test

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

DRW Services, Inc.

Contact Person: Douglas Harmon

Phone: (708) 758-3222 Contractor Registration # IL194 Exp. 3/10/2020

Sincerely,

Daniel Starks

Carrief J. Starks

cc: Storage Tank Safety Specialist Division File