

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 1012095 Permit # 00821-2018UPG Request Rec'd 06/29/2018 Amended Date Approval Date 7/2/2018 DS Permit Expires 1/2/2019

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) **OWNER OF TANKS** - Corporation, partnership, or other business

entity:

Starved Rock Marina P.O. Box 2460 Ottawa, IL 61350

Contact: Ron Powers (815) 433-4218

(2) FACILITY - name and address where tanks are located:

Starved Rock Marina 1130 N 27th Road Ottawa, IL 61350

Contact: Ron Powers (815) 433-4218

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 5) 4,000, (TK # 6) 2,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 5) Gasoline, (TK # 6) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping: (TK # 5, 6) Leak Detect - Piping - Interstitial Monitoring

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Site has a Veeder Root system that the sump sensors are not working. We will replace them with the Morrison Alarm consoles 1-Dual channel 1-Single. We will add the 3-new sensors to detect liquid etc. We will then disconnect the veeder root sump sensors etc. NOTE: Sensors must shut down the submersible supplying that line upon detection of a leak per 175.640 a) 2)

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Pipeco, Inc. 610 29th Street Contact Person: Debbie Rindler Phone: (563) 344-0700 Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File