

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2021022 Permit # 01229-2018UPG Request Rec'd 09/04/2018 Amended Date Approval Date 9/4/2018 DS Permit Expires 3/5/2019

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

RDK Ventures, LLC 550 Warrenville Rd., Suite 400

Lisle, IL 60532

Contact: Charlene Troyer (630) 800-6065

(2) FACILITY - name and address where tanks are located:

Circle K #6758 401 West Madison Oak Park, IL 60302

Contact: Matthew Jordan (812) 379-9227

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1) 10,000, (TK # 2, 3) 8,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1, 2, 3) Piping Fiberglass Double Wall A.O. Smith, (TK # 1, 2, 3) Piping Shear Valves, (TK # 1, 2, 3) Piping Valves Ball Valve, (TK # 1, 2, 3) Piping Flex Connector Steel
- (d) Product to be stored in each tank: (TK # 1, 2, 3) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Installing new Bravo B1000 dispenser sumps in same locations as the existing sumps. Partial piping to accommodate the new sumps. New shear valves and ball valves. Rebuilding islands in the same locations as existing.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Anderson Pump Service, Inc. 19659 South 97th Avenue Contact Person: Ronald Anderson Phone: (708) 478-6190 Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File