

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2021806 Permit # 01371-2018UPG Request Rec'd 09/20/2018 Amended Date Approval Date 9/20/2018 DS Permit Expires 3/20/2019

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Kooshtard Property V, LLC 1370 Avenue of the Americas, 21st Floor

Contact: Charlene Troyer (630) 800-6065

(2) <u>FACILITY</u> - name and address where tanks are located:

Mac's #177 1952 East Court Street Kankakee, IL 60901

Contact: Renee Stephens (812) 379-9227

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 2) 10,000
- (b) Type of tanks:

New York, NY 10019

- (c) Type of piping: (TK # 2) Piping Other Steel Riser
- (d) Product to be stored in each tank: (TK # 2) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Replacing riser pipe and adapter on Tank #2. Pipe rusted out for inventory control probe and need to replace. **NOTE: Bung at tank is rusted out, per contractor. A** representative from the tank manufacturer will be on site to re-fiberglass at the bung to make the repair.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Pemco Service Company, Inc. 1040 East Second Street Contact Person: William "Butch" VonDrehle Phone: (815) 265-7364

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File