

### Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

## **FOR OFFICE USE ONLY**

Facility # 4013793 Permit # 01379-2018UPG Request Rec'd 09/21/2018 Amended Date Approval Date 9/24/2018 DS Permit Expires 3/26/2019

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) OWNER OF TANKS - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
OMSAI, LLC 1701 Philo Road	Urbana Minimart 1701 Philo Road Urbana, IL 61802

Contact: Mahendra Patel (618) 593-6478

Contact: Ankit Patel (217) 549-

### (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 14) 8,000
- (b) Type of tanks:

Urbana, IL 61802

- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 14) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices: (TK # 14) Overfill Prev Device Overfill Drop Tube Valve OPW 61SO
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Installing OPW 61SO as overfill prevention device on TANK#14 (RUL) due to FAILURE as reported by MIDWEST TANK TESTING

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Midwest Petroleum Service, LLC. 23535 North 1530 East Road Danville, IL 61834 Contact Person: Mike Hall Phone: (217) 443-2263 Contractor Registration # II 002306

Contractor Registration # IL002306 Exp. 6/26/2020

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File