

## Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

### **FOR OFFICE USE ONLY**

Facility #7024451 Permit #01493-2018UPG Request Rec'd 10/05/2018 Amended Date Approval Date 10/9/2018 DS Permit Expires 4/9/2019

### Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) **OWNER OF TANKS** - Corporation, partnership, or other business

entity:

Martin & Bayley, Inc. 1311 W. Main Street Carmi, IL 62821

Contact: Troy Dietz (618) 382-2334

(2) FACILITY - name and address where tanks are located:

Hucks #247 908 S. Court Marion, IL 62959

Contact: Jenna Akins (618) 993-3501

### (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 2) 10,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 2) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices: (TK # 2) Overfill Prev Device Overfill Drop Tube Valve Emco Wheaton A1100 Guardian
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Replace ball float with EMCO Wheaton A1100 Overfill Prevention Device.

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Hinderliter Construction & Maint., Inc. 3601 North St. Joseph Avenue Evansville, IN 47720

Contact Person: Mark Hinderliter Phone: (812) 425-4137 Contractor Registration # IL646 Exp. 4/2/2020 Daniel J. Starke

Daniel Starks

cc: Storage Tank Safety Specialist Division File