

## Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

# Permit for Emergency Repair Request on 10/5/2018

#### **FOR OFFICE USE ONLY**

Facility # 2023182 Permit # 01504-2018UPG Request Rec'd 10/08/2018 Amended Date Approval Date 10/9/2018 DS Permit Expires 10/22/2018

#### Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

PAK Properties, LLC d/b/a PAK Petroleum

9 Vennard Ct

Lombard, IL 60148-618

Contact: Imitiaz Memon (708) 220-9554

(2) FACILITY - name and address where tanks are located:

Elk Grove BP 601 E. Devon

Elk Grove Village, IL 60007

Contact: Fayazz Karim (708) 466-5467

## (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 4) 15,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 4) Piping Flexible Double Wall Total Containment Enviroflex non-corrosive
- (d) Product to be stored in each tank: (TK # 4) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Pipe line leaking under dispenser 7/8. Breaking pipe line at fittings below shear valve to replace leaking O-Ring. **NOTE:** If there is not a sump existing one must be installed under a separate upgrade permit per 175.410 d)

## (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Cardinal Compliance LLC 730 Creel Dr Wood Dale, IL 601910000 Contact Person: Chris Derro Phone: (708) 452-8620

Contractor Registration # IL002418 Exp. 3/16/2019

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File