

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2014573 Permit # 01624-2018UPG Request Rec'd 10/25/2018 Amended Date Approval Date 10/25/2018 DS Permit Expires 4/25/2019

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Speedway, LLC P.O. Box 1500 Springfield, OH 45501

Contact: Eric M. Swaisgood (937) 863-6513

(2) FACILITY - name and address where tanks are located:

Speedway #7540 948 North Farnsworth Ave. Aurora, IL 60605

Contact: Store Manager (937) 863-6513

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 2) 10,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 2) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 2) Spill Contain Device Single Wall Spill Bucket OPW 1C-2100C-PEVR
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) <u>SPECIAL CONTINGENCIES</u>:

After inspection overspill manhole on MUL tank has crack in it and need to be replaced Existing manhole was a OPW 101BG 5 gallon overspill and and will be replaced with a 1C2100C PEVR Grade Level

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

DRW Services, Inc.

Contact Person: Douglas Harmon
600 East Joe Orr Road

Phone: (708) 758-3222

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File