

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

Permit for Emergency Repair Request on 10/30/2018

FOR OFFICE USE ONLY

Facility # 2009882 Permit # 01648-2018UPG Request Rec'd 10/29/2018 Amended Date Approval Date 10/29/2018 DS Permit Expires 11/9/2018

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
Jaswinder Sandhu 336 Farmhill Circle	Lake Zurich Marathon 1125 Old Rand Road Lake Zurich, IL 60047
Contact I 1 Con II (0.47) 254 1792	Contact: Jaswinder Sandhu (847) 254-1782

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

Contact: Jaswinder Sandhu (847) 254-1782

- (a) Number and size of tanks being upgraded or repaired: (TK # 1) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1) Piping Steel Single Wall Piping, (TK # 1) Piping Fiberglass Double Wall Ameron Dualoy 3000/LCX, (TK # 1) Piping Ball Valves, (TK # 1) Piping Flex Connector Steel
- (d) Product to be stored in each tank: (TK # 1) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Due to a sump to tank adapter failure the Regular tank is taking on groundwater. The existing double walled fiberglass piping will be cut back so teh sump can be removed to access the failed adapter. The exisiting sump will be reset on the new adapter and the double walled piping will be run back into the sump with new galvanized steel fittings, flex connector and ball valve installed within the new sump.

B & K Equipment Company 2939 175th Street Lansing IL 60438 Contact Person: Ed Angell Phone: (708) 474-3344 Contractor Registration # IL1207 Exp. 2/14/2020

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File