

### Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

### **FOR OFFICE USE ONLY**

Facility # 6027735 Permit # 01660-2018UPG Request Rec'd 10/30/2018 Amended Date Approval Date 10/30/2018 DS Permit Expires 4/30/2019

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Mac's Convenience Stores, LLC 550 Warrenville Rd. Suite 400

Lisle, IL 60532

Contact: Charlene Troyer (331) 251-7343

(2) FACILITY - name and address where tanks are located:

Circle K #1346 10425 Lincoln Trail Fairview Heights, IL 62208

Contact: Jonathan Ross (812) 379-9227

## (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2, 3) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1) Piping Single Wall Submersible (STP) Sump OPW Flexworks Poly Sump
- (d) Product to be stored in each tank: (TK # 1, 2, 3) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 1, 2) Spill Contain Device Double Wall Spill Bucket Emco Wheaton A1004, (TK # 3) Spill Contain Device Double Wall Spill Bucket OPW ISC-3112D
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Upgrading and replacing the Premium Spill Bucket, Premium and NL STP Sump, and Dispenser # 3/4 Containment Sump.

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Neumayer Equipment Company, Inc. 5060 Arsenal Street St. Louis, MO 63139

Contact Person: Jimmy Spiros Phone: (314) 772-4501

Contractor Registration # IL1502 Exp. 3/26/2020

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File