



Office of the Illinois State Fire Marshal  
Division of Petroleum and Chemical Safety  
1035 Stevenson Drive  
Springfield, IL 62703  
2177851020

**FOR OFFICE USE ONLY**

Facility # 3037385  
Permit # 01793-2018UPG  
Request Rec'd 11/16/2018  
Amended Date  
Approval Date 11/19/2018 DS  
Permit Expires 5/21/2019

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

<p><b>(1) <u>OWNER OF TANKS</u></b> - Corporation, partnership, or other business entity:</p> <p>Road Ranger, LLC 4930 E. State Street Rockford, IL 61108  Contact: John Carabelli (815) 387-1700</p>	<p><b>(2) <u>FACILITY</u></b> - name and address where tanks are located:</p> <p>Road Ranger #186 1311 N. Carolyn Drive Minonk, IL 61760  Contact: Christina Hammer (815) 237-0100 Ext. 221</p>
---	---

**(3) UPGRADE OR REPAIR OF TANKS:**

(a) *Number and size of tanks being upgraded or repaired: (TK # 1, 2) - 15,000, (TK # 3, 4) - 8,000, (TK # 5) - 20,000*

(b) *Type of tanks:*

(c) *Type of piping:*

(d) *Product to be stored in each tank: (TK # 1, 4) - Diesel Fuel, (TK # 2, 3) - Gasoline, (TK # 5) - B-99*

(e) *Type of leak detection being used:*

*Tank: (TK # 1, 4, 5) Leak Detect - Tank - Automatic Tank Gauging Veeder Root TLS 350*

*Piping: (TK # 1, 2, 3, 4) Leak Detect - Piping - Electronic Pressurized Line Leak Detection Veeder Root TLS 350, (TK # 1, 2, 3, 4, 5) Leak Detect - Piping - Non-Discriminating Sump Sensor Interstitial Monitoring Veeder Root, (TK # 5) Leak Detect - Piping - American with Annual Prec Line Testing Suction*

(f) *Corrosion Protection being used:*

*Tank:*

*Piping:*

(g) *Spill containment devices, piping, and dispenser containmnt devices: (TK # 5) Spill Contain Device - Double Wall Spill Bucket OPW 1C-3112D Edge*

(h) *Overfill prevention devices: (TK # 5) Overfill Prev Device - Overfill Alarm Veeder Root TLS 350*

(i) *Manway accessible at grade:*

(4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at [www.sfm.illinois.gov](http://www.sfm.illinois.gov) or by calling (217)785-1020.

(5) **SPECIAL CONTINGENCIES** : Updating actual existing equipment per NOV by Travis Smith. No requirement for contractor to be present at final or notification form to be submitted per Fred Schneller.

**(6) PERSON, FIRM OR COMPANY PERFORMING WORK:**

Howard Lee & Sons Inc.

Contact Person: Vicky Buhl

4093 Perryville Road PO Box 446  
Cherry Valley, IL 61016

Phone: (815) 332-4966  
Contractor Registration # IL456 Exp. 3/20/2020

Sincerely,



---

Daniel Starks

cc: Storage Tank Safety Specialist  
Division File