

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2031882 Permit # 02004-2018UPG Request Rec'd 12/19/2018 Amended Date Approval Date 12/19/2018 DS Permit Expires 6/19/2019

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

entity:

RDK Ventures, LLC 550 Warrenville Rd., Suite 400 Lisle, IL 60532

Contact: Charlene Troyer (630) 800-6065

(2) FACILITY - name and address where tanks are located:

Circle K. #6748 1991 Maple Mundelein, IL 60060

Contact: Jack Nadulek (812) 379-9227

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2, 3) 12,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1, 2, 3) Piping Fiberglass Double Wall Ameron Dualoy 3000/LCX, (TK # 1, 2, 3) Piping Other Steel Riser, (TK # 1, 2, 3) Piping Other submersible pump, (TK # 1, 2, 3) Piping Ball Valves, (TK # 1, 2, 3) Piping Shear Valves, (TK # 1, 2, 3) Piping Flex Connector Steel, (TK # 1, 2, 3) Piping Single Wall Submersible (STP) Sump Bravo B-407-PP
- (d) Product to be stored in each tank: (TK # 1, 2, 3) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 1, 2, 3) Spill Contain Device Double Wall Spill Bucket OPW 1C-3112D Edge
- (h) Overfill prevention devices: (TK # 1, 2, 3) Overfill Prev Device Overfill Drop Tube Valve OPW 71SO-410C
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Repipe station per drawing. All new sumps for tanks and dispensers. Re-use all Veeder Root equipment. Relocate fills and stage 1 out of sumps to the end of the tanks. NOTE: Sight has existing sump sensors to be re-used

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Anderson Pump Service, Inc.

Contact Person: Ronald Anderson

19659 South 97th Avenue Mokena, IL 60448 Phone: (708) 478-6190 Contractor Registration # IL002275 Exp. 5/21/2020

Sincerely,

Daniel Starks

Carrief J. Starks

cc: Storage Tank Safety Specialist Division File