

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

Amended

FOR OFFICE USE ONLY

Facility # 4038592 Permit # 01892-2018UPG Request Rec'd 12/05/2018 Amended Date 01/07/2019 DS Approval Date 12/5/2018 DS Permit Expires 6/5/2019

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) OWNER OF TANKS - Corporation, partnership, or other business

entity:

Lanman Oil Company P.O. Box 108 Charleston, IL 61920

Contact: Mike Lanman (217) 348-8020

(2) <u>FACILITY</u> - name and address where tanks are located:

Lambo's Amoco III 100 Miller Road Mattoon, IL 61938

Contact: Amber Whitley (217) 235-1227

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1) 15,000, (TK # 2) 8,200
- (b) Type of tanks:
- (c) Type of piping: (TK # 1, 2) Piping Flexible Double Wall A.P.T. Poly Tech P175SC, (TK # 1) Piping Single Wall Transition Sump Bravo B-700 Series
- (d) Product to be stored in each tank: (TK # 1, 2) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping: (TK # 1) Leak Detect - Piping - Stand Alone Sensor Interstitial Monitoring Veeder Root non discriminating

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) <u>SPECIAL CONTINGENCIES</u>:

Had to add transition sump and sump sensor. **NOTE:** Sensor must shut down the submersible pump upon detection of a leak per 175.640 a) 1)

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Seneca Companies, Inc. 4140 East 14th Street PO Box 3360 Contact Person: Keri Hankins Phone: (816) 761-1270 Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File