

## Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

## **FOR OFFICE USE ONLY**

Facility # 6017351 Permit # 00191-2019UPG Request Rec'd 01/28/2019 Amended Date Approval Date 1/28/2019 DS Permit Expires 7/30/2019

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business

entity:

Martin & Bayley, Inc. 1311 W. Main Street Carmi, IL 62821

Contact: Landon Bayley (618) 382-2334

(2) FACILITY - name and address where tanks are located:

Hucks #351 1530 West Main Street Salem, IL 62881

Contact: Alyssa (618) 548-8225

## (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 6) 12,000, (TK # 7, 8) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 6, 7, 8) Piping Flexible Double Wall OPW Flexworks, (TK # 6, 7, 8) Piping Other submersible pump, (TK # 6, 7, 8) Piping Ball Valves, (TK # 6, 7, 8) Piping Single Wall Submersible (STP) Sump OPW Fiberglass
- (d) Product to be stored in each tank: (TK # 6) Gasoline Regular, (TK # 7) Gasoline Premium, (TK # 8) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping: (TK # 6, 7) Leak Detect - Piping - Mechanical Pressurized Line Leak Detection Red Jacket FX1V, (TK # 6, 7, 8) Leak Detect - Piping - Non-Discriminating Sump Sensor Interstitial Monitoring Veeder Root, (TK # 8) Leak Detect - Piping - Mechanical Pressurized Line Leak Detection Red Jacket FX1DV

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 6, 7, 8) Spill Contain Device Double Wall Spill Bucket OPW 1C-3132D Edge
- (h) Overfill prevention devices: (TK # 6, 7, 8) Overfill Prev Device Overfill Drop Tube Valve OPW 71SO-4000
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: All work has been completed. The original permit expired. We just need to sschedule the final.

Hinderliter Construction & Maint., Inc. 3601 North St. Joseph Avenue Evansville, IN 47720 Contact Person: Mark Hinderliter Phone: (812) 425-4137 Contractor Registration # IL646 Exp. 4/2/2020

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File