

## Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

## **FOR OFFICE USE ONLY**

Facility # 7035563 Permit # 00211-2019UPG Request Rec'd 01/31/2019 Amended Date Approval Date 1/31/2019 DS Permit Expires 7/31/2019

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
J.D. Streett & Company, Inc. 144 Weldon Parkway	Anna Citgo 414 East Vienna Anna, IL 62906
Contact: Darrell Meek (800) 678-6600	Contact: Lisa Graham (618) 833-9031

## (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1) 15,000, (TK # 2) 8,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 1) Gasoline Regular, (TK # 2) Gasoline Premium
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 1, 2) Spill Contain Device Double Wall Spill Bucket Franklin Fueling Systems Defender 705
- (h) Overfill prevention devices: (TK # 1, 2) Overfill Prev Device Overfill Drop Tube Valve Franklin Fueling Systems 708 Defender Series
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Installing new spill buckets and overfill drop tubes on both tanks. Installing new dispensers on the existing islands. **NOTE:** If dispensers are installed and no piping is broken at or below the shear valve then no containment sump test will be necessary, however per 175.410 e) if both the dispenser and the equipment needed to connect the dispenser to the UST are installed a sump and testing will be required.

UPC Enterprises, LC d/b/a United Petroleum Service 4444 Union Blvd.
St. Louis, MO 63115

Contact Person: Harvey Stokes Phone: (314) 241-3767 Contractor Registration # IL002402 Exp. 2/10/2020

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File