

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety 1035 Stevenson Drive Springfield, IL 62703 2177851020

## FOR OFFICE USE ONLY

Facility # 2040346 Permit # 00433-2019UPG Request Rec'd 03/08/2019 Amended Date Approval Date 3/11/2019 DS Permit Expires 9/11/2019

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
Meijer Great Lakes Limited Partnership 2929 Walker Avenue, NW	Meijer Gas Station #206 490 S Randall Rd Algonquin, IL 60102
Contact: Erik Petrovoskis (616) 453-6711	Contact: Dianna Murray (847) 960-7800 Ext. 479

## (3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 3) 8,000, (TK # 2) 20,000, (TK # 4) 3,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 1) Gasoline Premium, (TK # 2) Gasoline Regular, (TK # 3) Diesel Fuel, (TK # 4) Kerosene
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices: (TK # 1, 2, 3, 4) Overfill Prev Device Ball Only Removed Ball Float Vent Valve
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u> : all ball float ovefill prevention failed testig and will be disabled. The site will continue to use the existing alarm and drop tube overfill prevention for all tanks.

## (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

B & K Equipment Company 2939 175th Street Lansing, IL 60438 Contact Person: Ed Angell Phone: (708) 474-3344 Contractor Registration # IL1207 Exp. 2/14/2020 Sincerely,

Daniel J. Starke

Daniel Starks

cc: Storage Tank Safety Specialist Division File