

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility #3012534 Permit #00912-2019UPG Request Rec'd 05/09/2019 Amended Date Approval Date 5/9/2019 DS Permit Expires 11/12/2019

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

J&L 66

Santok, Inc.

3701 Washington Road

3701 Washington Road East Peoria, IL 61611

East Peoria, IL 61611

Contact: Raj Patel (309) 694-7188

Contact: Raj Patel (309) 694-7188

(2) FACILITY - name and address where tanks are located:

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2) 10,000, (TK # 3) 8,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1, 2, 3) Piping Fiberglass Double Wall Ameron Dualoy 3000/LCX from exsting tanks to existing dispensers, (TK # 1, 2, 3) Piping Ball Valves, (TK # 1, 2, 3) Piping Extractor Fitting Valves, (TK # 1, 2, 3) Piping Shear Valves, (TK # 1, 2, 3) Piping Flex Connector Steel, (TK # 1, 2, 3) Piping Single Wall STP/Tanktop Sump Franklin Fueling Systems 4542 Series Polyethylene. Installing new Franklin Fueling APT LMM-3914-36-W Poly dispenser sumps at the (4) new islands.
- (d) Product to be stored in each tank: (TK # 1) Gasoline Regular, (TK # 2) Gasoline Premium, (TK # 3) Gasoline Mid-grade
- (e) Type of leak detection being used:

Tank:

Piping: (TK # 1, 2, 3) Leak Detect - Piping - Electronic Pressurized Line Leak Detection Veeder Root TLS 350 PLLD leak sensors, (TK # 1, 2, 3) Leak Detect - Piping - Non-Discriminating Sump Sensor Interstitial Monitoring Veeder Root in all submersible and dispenser sumps. NOTE: Sensors must shut down the submersible pump supplying that line upon detection of a leak per 175..640 a) 1)

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 1, 2, 3) Spill Contain Device Single Wall Spill Bucket OPW 1SC-2100DEVR
- (h) Overfill prevention devices: (TK # 1, 2, 3) Overfill Prev Device Overfill Drop Tube Valve OPW 61SOP
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: NOTE: Dispensers meet the 10' separation required by our rules (175.450 f) 5)) from the building

and property lines. Contractor is repiping the gasoline side of this facility as well as installing new spill containment and overfill prevention. No ball floats are existing according to our database

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Total Petroleum Service Company 2421 Washington Road Washington, IL 61571 Contact Person: Greg McCoy Phone: (309) 694-8224

Contractor Registration # IL1079 Exp. 2/8/2020

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File