

# Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

# Amended

### **FOR OFFICE USE ONLY**

Facility # 4025056 Permit # 00782-2019UPG Request Rec'd 04/23/2019 Amended Date 05/28/2019 DS Approval Date 4/23/2019 DS Permit Expires 10/23/2019

### Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Casey's Retail Company P.O. Box 3004

Ankeny, IA 50021

Contact: Jill Reams-Widder (515) 965-6238

(2) FACILITY - name and address where tanks are located:

Casey's General Store #1515 523 E. IL Rt. 10 De Land, IL 61839

Contact: Nichole Duncan (515) 965-6238

#### (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1) 10,000, (TK # 2) 6,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1, 2) Piping Fiberglass Single Wall Piping Ameron, (TK # 1, 2) Piping Single Wall STP/Tanktop Sump Franklin Fueling Systems A4236-0/0-OB-S
- (d) Product to be stored in each tank: (TK # 1) Gasoline, (TK # 2) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 1, 2) Spill Contain Device Single Wall Spill Bucket EBW 705 CIGKT Defender
- (h) Overfill prevention devices: (TK # 1) Overfill Prev Device Overfill Drop Tube Valve OPW 61SOC, (TK # 2) Overfill Prev Device Overfill Drop Tube Valve EBW 705
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

# (5) <u>SPECIAL CONTINGENCIES</u>:

Upgrading all tank top components on both tanks. WE will be removing existing ball floats and installing new overfill droptubes. Adding tank and line tests

### (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Seneca Companies, Inc. 4140 East 14th Street PO Box 3360 Des Moines, IA 50313 Contact Person: Glen Davis Phone: (816) 761-1270

Contractor Registration # IL598 Exp. 2/23/2020

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File