

## Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

## **FOR OFFICE USE ONLY**

Facility # 1027328 Permit # 00975-2019UPG Request Rec'd 05/10/2019 Amended Date Approval Date 5/28/2019 DS Permit Expires 11/30/2019

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business

entity:

Johnson Oil Company 1305 12th Avenue Rock Falls, IL 61071

Contact: Kathy Peugh (815) 625-6380

(2) FACILITY - name and address where tanks are located:

Express Lane Gas & Food Mart Inc 4702-4712 West State Rockford, IL 61102

Contact: Linda Heaulin (815) 625-6380

## (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2) 8,200, (TK # 3) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1, 2, 3) Piping Other Steel Riser
- (d) Product to be stored in each tank: (TK # 1) Gasoline Premium, (TK # 2) Gasoline Mid-grade, (TK # 3) Gasoline Regular
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 1, 2, 3) Spill Contain Device Single Wall Spill Bucket EBW 705
- (h) Overfill prevention devices: (TK # 1, 2, 3) Overfill Prev Device Overfill Alarm EBW Auto-Stik II
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: adding overfill alarm for overfill protection, all tanks. On tank 2 & 3 installing new EBW 705 manhole and new riser. **NOTE:** Ball floats will be removed or disabled per contractor

$\sim$					MING WORK
ını	PHRSON	HIRVICIR	CUNIPAN	IY PHRHUKI	MING - VM JRK

Illowa Enterprises, Inc. 2703 4th Avenue Contact Person: Rob Vyncke Phone: (309) 762-1729 Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File