

### Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

### **FOR OFFICE USE ONLY**

Facility # 3026385 Permit # 01100-2019UPG Request Rec'd 06/07/2019 Amended Date Approval Date 6/10/2019 DS Permit Expires 12/10/2019

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Thorntons LLC 2600 James Thornton Way Louisville, KY 40245

Contact: Shawn Orr (502) 425-8022

(2) FACILITY - name and address where tanks are located:

Thornton Oil #352 2255 E. Washington East Peoria, IL 61611

Contact: Angela Noll (217) 735-4493

## (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2, 3, 4) 12,000, (TK # 5, 6) 8,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 1) Gasoline Premium, (TK # 2, 3) Gasoline Regular, (TK # 4) Gasoline Mid-grade, (TK # 5) Diesel Fuel, (TK # 6) Kerosene
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices: (TK # 1, 2, 3, 4) Overfill Prev Device Overfill Drop Tube Valve OPW 61SO, (TK # 5, 6) Overfill Prev Device Overfill Drop Tube Valve OPW 71SO-410C
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) SPECIAL CONTINGENCIES: Removing ball floats from all tanks and installing overfill drop tube valves

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Seneca Companies, Inc. 4140 East 14th Street PO Box 3360 Des Moines, IA 50313 Contact Person: Glen Davis Phone: (816) 761-1270

Contractor Registration # IL598 Exp. 2/23/2020

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File