

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety 1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2021204 Permit # 01558-2019UPG Request Rec'd 08/19/2019 Amended Date Approval Date 8/19/2019 DS Permit Expires 2/19/2020

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
RDK Ventures, LLC	Circle K #6808
550 Warrenville Rd., Suite 400	1411 Park Avenue
Lisle, IL 60532	Highland Park, IL 60035
Contact: Charlene Troyer (630) 800-6065	Contact: Mike Kyle (812) 379-9227

(3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 5, 6) 15,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 5, 6) Piping Other Steel Riser
- (d) Product to be stored in each tank: (TK # 5) Gasoline Regular, (TK # 6) Gasoline Premium
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 5, 6) Spill Contain Device Single Wall Spill Bucket OPW 1-2100 DSH
- (h) Overfill prevention devices: (TK # 5, 6) Overfill Prev Device Overfill Drop Tube Valve Emco Wheaton A1100 Guardian
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfmillinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Replace spill container, vapor spill container, drop tube and risers on both tanks. **NOTE: No ball floats listed in our system**

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Anderson Pump Service, Inc. 19659 South 97th Avenue Mokena, IL 60448 Contact Person: Ron Anderson Phone: (708) 478-6190 Contractor Registration # IL002275 Exp. 5/21/2020 Sincerely,

Daniel J. Starke

Daniel Starks

cc: Storage Tank Safety Specialist Division File