

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2013815 Permit # 01909-2019UPG Request Rec'd 10/07/2019 Amended Date Approval Date 10/7/2019 DS Permit Expires 4/7/2020

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

•

BBT Properties, Inc. 11 Shelburne Dr. Oak Brook, IL 60523

Contact: Ravi Harsoor (630) 923-1826

(2) FACILITY - name and address where tanks are located:

Rolling Meadows Marathon 4200 Kirchoff Rolling Meadows, IL 60008

Contact: Ravi Harsoor (630) 923-1826

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2, 3) 10,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 1) Gasoline Regular, (TK # 2) Diesel Fuel, (TK # 3) Gasoline Premium
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 1, 2, 3) Spill Contain Device Single Wall Spill Bucket OPW 1C-2100-DEVR
- (h) Overfill prevention devices: (TK # 1, 2, 3) Overfill Prev Device Ball Only Removed Ball Float Vent Valve, (TK # 1, 2, 3) Overfill Prev Device Overfill Drop Tube Valve OPW 71SO-400C
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: removal of ball floats and installation of overfill prevention drop tubes and installation of opw spill buckets on all three tanks

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Reliable Pump Service and Maintenance 14007 S Bell Road Suite 228 Contact Person: John Baio, Jr. Phone: (815) 546-7867

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File